

LOT NO :

# G-MART CORPORATION SDN BHD

## INSPECTION REPORT

GRADING :
2E

REGN. NUMBER :	YEAR :	REGISTRATION :						
<b>MBD8474</b>		<table border="1" style="width: 100%;"> <tr> <td> </td> <td> </td> <td> </td> </tr> <tr> <td>DAY</td> <td>MONTH</td> <td>YEAR</td> </tr> </table>				DAY	MONTH	YEAR
DAY	MONTH	YEAR						

LEGAL OWNER HISTORY : TNB			
INDIVIDU	COMPANY	GOVERNMENT	
RENTAL	PERSONAL USED	COMPANY USED	EX-TAXI

MAKE , MODEL AND VARIANT :	DISPLACEMENT :	KEY :	SPARE KEY :
<b>PERODUA RUSA</b>		<b>Y N</b>	<b>Y N</b>

ODOMETER :	TRANSMISSION :	WHEEL DRIVE :	FUEL :	NO. OF SEAT :	PRESENTATION :
	<b>AT MT</b>	<b>2WD 4WD</b>	<b>P D H</b>	<b>4</b>	<b>DRIVE TOWING</b>


EXTERIOR COLOUR :	INTERIOR COLOUR :	TOOLS :			
<b>RED</b>	<b>GREY</b>	<b>SPARE TYRE</b>	<b>JACK</b>	<b>TOOL SET</b>	
ORIGINAL CHANGE	ORIGINAL CHANGE	YES NO	YES NO	YES NO	NO

ENGINE NO :
<b>WOT2041</b>

CHASSIS NO :
<b>PM2S92V0062012748</b>

EQUIPMENT ORIGINAL	<b>A/COND</b>	<b>SUNROOF</b>	<b>ALLOW RIMS</b>	<b>AIRBAGS</b>
	GOOD FAIL	GOOD FAIL	GOOD FAIL	GOOD FAIL
	<b>POWER STEERING</b>	<b>POWER WINDOWS</b>	<b>LEATHER</b>	<b>NAVI</b>
	GOOD FAIL	GOOD FAIL	GOOD FAIL	GOOD FAIL

AFTERMARKET ACCESSORIES :



LEGEND :  
**S: Scratch C: Cracked D: Dented B: Broken F: Faded L: Loosed R: Rusty SD: Scratch & Dented X: Part Exchange Need XX: Part Exchange History W: Repair History**

NOTES :
GEAR BOX PROBLEM

INSPECTOR REPORT :