

LOT NO :

# G-MART CORPORATION SDN BHD

## INSPECTION REPORT

GRADING :
2E

REGN. NUMBER :	YEAR :	REGISTRATION :	LEGAL OWNER HISTORY :	TNB							
<b>WFU4538</b>	<b>1997</b>	<table border="1" style="width: 100px; height: 20px;"><tr><td> </td><td> </td><td> </td></tr><tr><td>DAY</td><td>MONTH</td><td>YEAR</td></tr></table>				DAY	MONTH	YEAR	INDIVIDU	COMPANY	GOVERNMENT
DAY	MONTH	YEAR									
			RENTAL	PERSONAL USED	COMPANY USED	EX-TAXI					

MAKE , MODEL AND VARIANT :	DISPLACEMENT :	KEY :	SPARE KEY :					
<b>MAN</b>	<table border="1" style="width: 100px; height: 20px;"><tr><td> </td></tr></table>		<table border="1" style="width: 40px; height: 20px;"><tr><td>Y</td><td>N</td></tr></table>	Y	N	<table border="1" style="width: 40px; height: 20px;"><tr><td>Y</td><td>N</td></tr></table>	Y	N
Y	N							
Y	N							


ODOMETER :	TRANSMISSION :	WHEEL DRIVE :	FUEL :	NO. OF SEAT :	PRESENTATION :										
<b>174087</b>	<table border="1" style="width: 40px; height: 20px;"><tr><td>AT</td><td>MT</td></tr></table>	AT	MT	<table border="1" style="width: 60px; height: 20px;"><tr><td>2WD</td><td>4WD</td></tr></table>	2WD	4WD	<table border="1" style="width: 60px; height: 20px;"><tr><td>P</td><td>D</td><td>H</td></tr></table>	P	D	H	<table border="1" style="width: 40px; height: 20px;"><tr><td>2</td></tr></table>	2	<table border="1" style="width: 60px; height: 20px;"><tr><td>DRIVE</td><td>TOWING</td></tr></table>	DRIVE	TOWING
AT	MT														
2WD	4WD														
P	D	H													
2															
DRIVE	TOWING														

EXTERIOR COLOUR :	INTERIOR COLOUR :	TOOLS :															
<table border="1" style="width: 100px; height: 20px;"><tr><td><b>WHITE</b></td></tr><tr><td>ORIGINAL</td><td>CHANGE</td></tr></table>	<b>WHITE</b>	ORIGINAL	CHANGE	<table border="1" style="width: 100px; height: 20px;"><tr><td><b>GREY</b></td></tr><tr><td>ORIGINAL</td><td>CHANGE</td></tr></table>	<b>GREY</b>	ORIGINAL	CHANGE	<table border="1" style="width: 100%;"><tr><td><b>SPARE TYRE</b></td><td><b>JACK</b></td><td><b>TOOL SET</b></td></tr><tr><td>YES</td><td>NO</td><td>YES</td><td>NO</td><td>YES</td><td>NO</td></tr></table>	<b>SPARE TYRE</b>	<b>JACK</b>	<b>TOOL SET</b>	YES	NO	YES	NO	YES	NO
<b>WHITE</b>																	
ORIGINAL	CHANGE																
<b>GREY</b>																	
ORIGINAL	CHANGE																
<b>SPARE TYRE</b>	<b>JACK</b>	<b>TOOL SET</b>															
YES	NO	YES	NO	YES	NO												

ENGINE NO :	CHASSIS NO :	
<table border="1" style="width: 100%; height: 20px;"><tr><td> </td></tr></table>		<b>M520073S071</b>

ORIGINAL EQUIPMENT	<b>A/COND</b>	<b>SUNROOF</b>	<b>ALLOW RIMS</b>	<b>AIRBAGS</b>				
	GOOD	FAIL	GOOD	FAIL	GOOD	FAIL	GOOD	FAIL
	<b>POWER STEERING</b>	<b>POWER WINDOWS</b>	<b>LEATHER</b>	<b>NAVI</b>				
	GOOD	FAIL	GOOD	FAIL	GOOD	FAIL	GOOD	FAIL

AFTERMARKET ACCESSORIES :



LEGEND :  
**S: Scratch C: Cracked D: Dented B: Broken F: Faded L: Loosed R: Rusty SD: Scratch & Dented X: Part Exchange Need XX: Part Exchange History W: Repair History**

NOTES :
ENGINE NOT COMPLETE

INSPECTOR REPORT :
--------------------