

LOT NO :

# G-MART CORPORATION SDN BHD

## INSPECTION REPORT

GRADING :
2D

REGN. NUMBER :	YEAR :	REGISTRATION :						
<b>WGN2143</b>	<b>1998</b>	<table border="1" style="width: 100%;"> <tr> <td> </td> <td> </td> <td> </td> </tr> <tr> <td>DAY</td> <td>MONTH</td> <td>YEAR</td> </tr> </table>				DAY	MONTH	YEAR
DAY	MONTH	YEAR						

LEGAL OWNER HISTORY :	TNB		
INDIVIDU	COMPANY	GOVERNMENT	
RENTAL	PERSONAL USED	COMPANY USED	EX-TAXI

MAKE , MODEL AND VARIANT :	DISPLACEMENT :	KEY :	SPARE KEY :				
<b>PERODUA KANCIL</b>		<table border="1" style="display: inline-table;"> <tr><td><b>Y</b></td><td><b>N</b></td></tr> </table>	<b>Y</b>	<b>N</b>	<table border="1" style="display: inline-table;"> <tr><td><b>Y</b></td><td><b>N</b></td></tr> </table>	<b>Y</b>	<b>N</b>
<b>Y</b>	<b>N</b>						
<b>Y</b>	<b>N</b>						


ODOMETER :	TRANSMISSION :	WHEEL DRIVE :	FUEL :	NO. OF SEAT :	PRESENTATION :
	<b>AT</b> <b>MT</b>	<b>2WD</b> <b>4WD</b>	<b>P</b> <b>D</b> <b>H</b>	<b>5</b>	<b>DRIVE</b> <b>TOWING</b>

EXTERIOR COLOUR :	INTERIOR COLOUR :	TOOLS :							
<b>RED</b>	<b>GREY</b>	<table border="1" style="display: inline-table;"> <tr> <td>SPARE TYRE</td> <td>JACK</td> <td>TOOL SET</td> </tr> <tr> <td><b>YES</b></td> <td><b>NO</b></td> <td><b>YES</b></td> <td><b>NO</b></td> </tr> </table>	SPARE TYRE	JACK	TOOL SET	<b>YES</b>	<b>NO</b>	<b>YES</b>	<b>NO</b>
SPARE TYRE	JACK	TOOL SET							
<b>YES</b>	<b>NO</b>	<b>YES</b>	<b>NO</b>						
ORIGINAL    CHANGE	ORIGINAL    CHANGE	YES    NO    YES    NO    YES    NO							

ENGINE NO :	CHASSIS NO :
<b>NO46814</b>	<b>PM2L201S002046464</b>

EQUIPMENT ORIGINAL	<b>A/COND</b>	<b>SUNROOF</b>	<b>ALLOW RIMS</b>	<b>AIRBAGS</b>
	GOOD    FAIL	GOOD    FAIL	GOOD    FAIL	GOOD    FAIL
	<b>POWER STEERING</b>	<b>POWER WINDOWS</b>	<b>LEATHER</b>	<b>NAVI</b>
	GOOD    FAIL	GOOD    FAIL	GOOD    FAIL	GOOD    FAIL

AFTERMARKET ACCESSORIES :



LEGEND :  
**S: Scratch C: Cracked D: Dented B: Broken F: Faded L: Loosed R: Rusty SD: Scratch & Dented X: Part Exchange Need XX: Part Exchange History W: Repair History**

NOTES :

INSPECTOR REPORT :