

LOT NO :

# G-MART CORPORATION SDN BHD

## INSPECTION REPORT

GRADING :
3C

REGN. NUMBER :	YEAR :	REGISTRATION :						
<b>QKD30</b>	<b>05/10</b>	<table border="1" style="width: 100%;"> <tr> <td> </td> <td> </td> <td> </td> </tr> <tr> <td>DAY</td> <td>MONTH</td> <td>YEAR</td> </tr> </table>				DAY	MONTH	YEAR
DAY	MONTH	YEAR						

LEGAL OWNER HISTORY :	HLFB							
<table border="1" style="width: 100%;"> <tr> <td>INDIVIDU</td> <td>COMPANY</td> <td>GOVERNMENT</td> </tr> <tr> <td>RENTAL</td> <td>PERSONAL USED</td> <td>COMPANY USED</td> <td>EX-TAXI</td> </tr> </table>	INDIVIDU	COMPANY	GOVERNMENT	RENTAL	PERSONAL USED	COMPANY USED	EX-TAXI	
INDIVIDU	COMPANY	GOVERNMENT						
RENTAL	PERSONAL USED	COMPANY USED	EX-TAXI					

MAKE , MODEL AND VARIANT :	DISPLACEMENT :	KEY :	SPARE KEY :
<b>TOYOTA ALPHARD 3.0</b>		<b>Y N</b>	<b>Y N</b>


ODOMETER :	TRANSMISSION :	WHEEL DRIVE :	FUEL :	NO. OF SEAT :	PRESENTATION :
<b>83648</b>	<b>AT MT</b>	<b>2WD 4WD</b>	<b>P D H</b>	<b>6</b>	<b>DRIVE TOWING</b>

EXTERIOR COLOUR :	INTERIOR COLOUR :	TOOLS :						
<b>WHITE</b>	<b>GREY</b>	<table border="1" style="width: 100%;"> <tr> <td>SPARE TYRE</td> <td>JACK</td> <td>TOOL SET</td> </tr> <tr> <td>YES NO</td> <td>YES NO</td> <td>YES NO</td> </tr> </table>	SPARE TYRE	JACK	TOOL SET	YES NO	YES NO	YES NO
SPARE TYRE	JACK	TOOL SET						
YES NO	YES NO	YES NO						
ORIGINAL CHANGE	ORIGINAL CHANGE							

ENGINE NO :	CHASSIS NO :
	<b>MNH10060209</b>

EQUIPMENT	<b>A/COND</b>	<b>SUNROOF</b>	<b>ALLOW RIMS</b>	<b>AIRBAGS</b>
	GOOD FAIL	GOOD FAIL	GOOD FAIL	GOOD FAIL
	<b>POWER STEERING</b>	<b>POWER WINDOWS</b>	<b>LEATHER</b>	<b>NAVI</b>
	GOOD FAIL	GOOD FAIL	GOOD FAIL	GOOD FAIL

AFTERMARKET ACCESSORIES :



LEGEND :  
**S: Scratch C: Cracked D: Dented B: Broken F: Faded L: Loosed R: Rusty SD: Scratch & Dented X: Part Exchange Need XX: Part Exchange History W: Repair History**

NOTES :

INSPECTOR REPORT :