

LOT NO :

# G-MART CORPORATION SDN BHD

## INSPECTION REPORT

GRADING :
2D

REGN. NUMBER :	YEAR :	REGISTRATION :	LEGAL OWNER HISTORY :	TNB													
<b>CAL6743</b>	<b>1994</b>	<table border="1" style="width: 100%;"><tr><td> </td><td> </td><td> </td></tr><tr><td>DAY</td><td>MONTH</td><td>YEAR</td></tr></table>				DAY	MONTH	YEAR	<table border="1" style="width: 100%;"><tr><td>INDIVIDU</td><td>COMPANY</td><td>GOVERNMENT</td></tr><tr><td>RENTAL</td><td>PERSONAL USED</td><td>COMPANY USED</td><td>EX-TAXI</td></tr></table>	INDIVIDU	COMPANY	GOVERNMENT	RENTAL	PERSONAL USED	COMPANY USED	EX-TAXI	
DAY	MONTH	YEAR															
INDIVIDU	COMPANY	GOVERNMENT															
RENTAL	PERSONAL USED	COMPANY USED	EX-TAXI														

MAKE , MODEL AND VARIANT :	DISPLACEMENT :	KEY :	SPARE KEY :					
<b>ISUZU AERIAL</b>	<table border="1" style="width: 100%;"><tr><td> </td></tr></table>		<table border="1" style="width: 100%;"><tr><td>Y</td><td>N</td></tr></table>	Y	N	<table border="1" style="width: 100%;"><tr><td>Y</td><td>N</td></tr></table>	Y	N
Y	N							
Y	N							


ODOMETER :	TRANSMISSION :	WHEEL DRIVE :	FUEL :	NO. OF SEAT :	PRESENTATION :										
<b>9395309</b>	<table border="1" style="width: 100%;"><tr><td>AT</td><td>MT</td></tr></table>	AT	MT	<table border="1" style="width: 100%;"><tr><td>2WD</td><td>4WD</td></tr></table>	2WD	4WD	<table border="1" style="width: 100%;"><tr><td>P</td><td>D</td><td>H</td></tr></table>	P	D	H	<table border="1" style="width: 100%;"><tr><td>3</td></tr></table>	3	<table border="1" style="width: 100%;"><tr><td>DRIVE</td><td>TOWING</td></tr></table>	DRIVE	TOWING
AT	MT														
2WD	4WD														
P	D	H													
3															
DRIVE	TOWING														

EXTERIOR COLOUR :	INTERIOR COLOUR :	TOOLS :															
<table border="1" style="width: 100%;"><tr><td><b>BLUE</b></td></tr><tr><td>ORIGINAL</td><td>CHANGE</td></tr></table>	<b>BLUE</b>	ORIGINAL	CHANGE	<table border="1" style="width: 100%;"><tr><td><b>BLUE</b></td></tr><tr><td>ORIGINAL</td><td>CHANGE</td></tr></table>	<b>BLUE</b>	ORIGINAL	CHANGE	<table border="1" style="width: 100%;"><tr><td>SPARE TYRE</td><td>JACK</td><td>TOOL SET</td></tr><tr><td>YES</td><td>NO</td><td>YES</td><td>NO</td><td>YES</td><td>NO</td></tr></table>	SPARE TYRE	JACK	TOOL SET	YES	NO	YES	NO	YES	NO
<b>BLUE</b>																	
ORIGINAL	CHANGE																
<b>BLUE</b>																	
ORIGINAL	CHANGE																
SPARE TYRE	JACK	TOOL SET															
YES	NO	YES	NO	YES	NO												

ENGINE NO :	CHASSIS NO :
<b>493841</b>	<b>JAANPR58LM7104872</b>

EQUIPMENT	<b>A/COND</b>	<b>SUNROOF</b>	<b>ALLOW RIMS</b>	<b>AIRBAGS</b>				
	GOOD	FAIL	GOOD	FAIL	GOOD	FAIL	GOOD	FAIL
	<b>POWER STEERING</b>	<b>POWER WINDOWS</b>	<b>LEATHER</b>	<b>NAVI</b>				
	GOOD	FAIL	GOOD	FAIL	GOOD	FAIL	GOOD	FAIL

AFTERMARKET ACCESSORIES :



LEGEND :  
**S: Scratch C: Cracked D: Dented B: Broken F: Faded L: Loosed R: Rusty SD: Scratch & Dented X: Part Exchange Need XX: Part Exchange History W: Repair History**

NOTES :

INSPECTOR REPORT :