

LOT NO :

G-MART CORPORATION SDN BHD

INSPECTION REPORT

TNB

REGN. NUMBER :	YEAR :	REGISTRATION :	LEGAL OWNER HISTORY :															
BDU2129	1993	<table border="1" style="width: 100%;"> <tr> <td> </td> <td> </td> <td> </td> </tr> <tr> <td>DAY</td> <td>MONTH</td> <td>YEAR</td> </tr> </table>				DAY	MONTH	YEAR	<table border="1" style="width: 100%;"> <tr> <td>INDIVIDU</td> <td>COMPANY</td> <td>GOVERNMENT</td> </tr> <tr> <td>RENTAL</td> <td>PERSONAL USED</td> <td>COMPANY USED</td> </tr> <tr> <td> </td> <td> </td> <td>EX-TAXI</td> </tr> </table>	INDIVIDU	COMPANY	GOVERNMENT	RENTAL	PERSONAL USED	COMPANY USED			EX-TAXI
DAY	MONTH	YEAR																
INDIVIDU	COMPANY	GOVERNMENT																
RENTAL	PERSONAL USED	COMPANY USED																
		EX-TAXI																

MAKE , MODEL AND VARIANT :	DISPLACEMENT :	KEY :	SPARE KEY :
ISUZU		Y N	Y N


ODOMETER :	TRANSMISSION :	WHEEL DRIVE :	FUEL :	NO. OF SEAT :	PRESENTATION :
	AT MT	2WD 4WD	P D H	3	DRIVE TOWING

EXTERIOR COLOUR :	INTERIOR COLOUR :	TOOLS :						
WHITE	GREY	<table border="1" style="width: 100%;"> <tr> <td>SPARE TYRE</td> <td>JACK</td> <td>TOOL SET</td> </tr> <tr> <td>YES NO</td> <td>YES NO</td> <td>YES NO</td> </tr> </table>	SPARE TYRE	JACK	TOOL SET	YES NO	YES NO	YES NO
SPARE TYRE	JACK	TOOL SET						
YES NO	YES NO	YES NO						
ORIGINAL CHANGE	ORIGINAL CHANGE							

ENGINE NO :	CHASSIS NO :
6B01600665	JAFSR11NK3604313

EQUIPMENT	A/COND	SUNROOF	ALLOW RIMS	AIRBAGS
	GOOD FAIL	GOOD FAIL	GOOD FAIL	GOOD FAIL
	POWER STEERING	POWER WINDOWS	LEATHER	NAVI
	GOOD FAIL	GOOD FAIL	GOOD FAIL	GOOD FAIL

<u>AFTERMARKET ACCESSORIES :</u>



LEGEND :
S: Scratch C: Cracked D: Dented B: Broken F: Faded L: Loosed R: Rusty SD: Scratch & Dented X: Part Exchange Need XX: Part Exchange History W: Repair History

NOTES :

INSPECTOR REPORT :